

Required Parts for NTMS Build #3		
Placed	Top to bottom, left to right	
	1	L5 near JP3
	2	U5
	3	U3
	5	ATTINY85
	9	U1
	11	L2 near JP1
	12	L6 near JP4
	13	U6
	14	U36
	15	D36 zener leaded
	17	RV1 optional else bridge pads
	18	U32
	19	Q32
	20	U33
	23	Q31
	28	3 header pins
	29	SMA connectors
	30	PTT connector
	31	+6.5v connector
	32	Fuse holder

Do not overheat. Cont chk=.27 ohm
Do not overheat. Cont chk=.27 ohm
Do not overheat. Cont chk=.27 ohm
High heat on ground tab
High heat on ground tab