

Required Parts for NTMS Build#4 JLCPCB boards		
Placed	Top to bottom, left to right	
	1	L5 near JP3
	2	L53 near JP51
	3	L54 near JP52
	4	U5
	5	U3
	6	ATTINY85
	7	U1
	8	L2 near JP1
	9	L6 near JP4
	10	U6
	11	U36
	12	D36 zener leaded
	13	RV1
	14	U32
	15	Q32
	16	U33
	17	3 header pins
	18	SMA connectors
	19	PTT connector
	20	+6.5v connector
	21	Fuse holder

Do not overheat. Cont chk=.27 ohm
Do not overheat. Cont chk=.27 ohm
Do not overheat. Cont chk=.27 ohm
High heat on ground tab
High heat on ground tab